

**INDEPENDENT VOLVO
SERVICE**

1401 THIRD ST. N.W.
ALBUQUERQUE NM 87102
ALBUQUERQUE NM 87102

(505) 247-9771

ivs@lobo.net

Estimate: **29428** 4/30/2008

AUTO SHOPPE IMPORTS

6616 Central Ave. Se
Albuquerque NM 87108

04212008 (505) 250-1120 p

**2001 Volvo C70 License: 3162/6932 Odometer: 73093 Vin: YV1NK53DX1J026932
5B5234T3 AW55-50/51SN ABS DARK GREY PEARL**

PRESALE INSPECTION AND BASIC MAINTENANCE

Labor performed on this job:

Labor 1 Labor Rate: \$85.00 \$85.00
INSPECT VEHICLE IN ORDER TO DETERMINE SERVICE
NEEDS BEFORE SALE

8

Parts:	\$0.00
Labor:	\$85.00
Job Subtotal:	\$85.00

SERVICE WORK

Labor performed on this job:

Labor 3 Labor Rate: \$85.00 \$255.00

Oil and filter service. Replace air filter, cabin air filter, fuel filter, wiper blades, upper engine stabilizer bushing and thermostat. Check brakes: Front 80% and Rear 50% remaining. Check fault codes: none found.

1

Parts required on this job:

Haz Mat Fee	6	\$0.25	\$1.50
10W30	6	\$2.50	\$15.00
OIL FILTER, INSERT 70 99-04 V	1	\$8.42	\$8.42
WASHER, DRAIN PLUG - ALUMINIUM 850, 960,	1	\$0.64	\$0.64
GASKET, OIL FILLER CAP 200 4CYL,	1	\$1.50	\$1.50
AIR FILTER, 850 ALL, C	1	\$16.50	\$16.50
WIPER BLADE KIT, FRONT (2PC) 850 94-98,	1	\$27.63	\$27.63
FILTER, FRESH AIR CABIN 850 ALL, C	1	\$26.19	\$26.19
FUEL FILTER, 850, 940 9	1	\$41.05	\$41.05
TORQUE MOTOR MOUNT, UPPER TO STAY ROD C70 99-04,	1	\$59.51	\$59.51
THERMOSTAT, COOLANT 90C 850, 960,	1	\$20.96	\$20.96
Fuel	1	\$23.00	\$23.00

Parts: \$241.90
Labor: \$255.00
Job Subtotal: \$496.90

MASTER KEY WITH SOFTWARE DOWNLOAD

Labor performed on this job:

Labor 0.5 Labor Rate: \$85.00 \$42.50

Supply new master key and download software to make it operate

1

Parts required on this job:

PASS KEY	1	\$47.25	\$47.25
IGNITION KEY APPL.	1	\$35.00	\$35.00

Parts: \$82.25
Labor: \$42.50
Job Subtotal: \$124.75

SUNROOF

Labor performed on this job:

Labor 3 Labor Rate: \$85.00 \$255.00

Sunroof sluggish, diagnose and replace worn sunroof guide rails.

8

Parts required on this job:

GUIDE RAIL, LEFT 1 \$271.30 \$271.30
SUNROOF 850, S/C70

GUIDE RAIL, RIGHT 1 \$271.30 \$271.30
SUNROOF 850, S/C70

Parts: \$542.60

Labor: \$255.00

Job Subtotal: \$797.60

BATTERY + CABLE

Labor performed on this job:

Labor 1.5 Labor Rate: \$85.00 \$127.50

Inspection revealed poor electrical connection at fuse box lug. Remove and replace "B+" cable

8

Parts required on this job:

CABLE, BATTERY 1 \$64.24 \$64.24
POSITIVE AUX S/C70,
V70 -00

Parts: \$64.24

Labor: \$127.50

Job Subtotal: \$191.74

SUSPENSION: UPPER SPRING SEAT RIGHT

Labor performed on this job:

Labor 1.2 Labor Rate: \$85.00 \$102.00

REMOVE RIGHT FRONT STRUT ASSEMBLY,
DISASSEMBLE STRUT AND REPLACE UPPER SPRING
SEAT. REASSEMBLE AND REINSTALL STRUT
ASSEMBLY.

8

Parts required on this job:

SPRING SEAT, FOR 1 \$38.99 \$38.99
STRUT

Parts: \$38.99

Labor: \$102.00

Job Subtotal: \$140.99

TURBO OIL RETURN TUBE

Labor performed on this job:

Labor 1 Labor Rate: \$85.00 \$85.00

Turbocharger oil return tube is leaking. Remove oil return tube, clean and reinstall using new gasket and o-ring seal.

8

Parts required on this job:

GASKET, TURBO OIL 1 \$2.07 \$2.07
RETURN

SEAL RING, TURBO OIL 1 \$1.95 \$1.95
RETURN PIPE

Parts: \$4.02

Labor: \$85.00

Job Subtotal: \$89.02

EMISSION TEST(FLEET)

Labor performed on this job:

Labor 0.1882 Labor Rate: \$85.00 \$16.00

PERFORM BERNILILLO COUNTY EMISSION TEST

1

Parts: \$0.00

Labor: \$16.00

Job Subtotal: \$16.00

SHOP INFORMATION AND SUPPORT

Labor performed on this job:

Labor 0.24 Labor Rate: \$85.00 \$20.40

The information age has arrived and it is expensive. We currently spend in excess of \$1000 monthly for current Volvo service information and hardware associated with its use. Additionally, the myriad of items never invoiced i.e. Hardware, chemicals, cleaner and other supplies continue to escalate in cost. Our shuttle service is another new expense. This surcharge is to help recover a portion of these costs without increasing our labor rate. Thank you for your understanding and support.

9

Parts: \$0.00

Labor: \$20.40

Job Subtotal: \$20.40

Estimate of Repair

Parts: \$974.00

Labor: \$988.40

Discounts: **(\$235.49)**

Subtotal: \$1,962.40

Tax: \$0.00

Total: \$1,726.91