

**INDEPENDENT VOLVO  
SERVICE**

Estimate: **29430** 4/30/2008

**AUTO SHOPPE IMPORTS**

1401 THIRD ST. N.W.  
ALBUQUERQUE NM 87102  
ALBUQUERQUE NM 87102

6616 Central Ave. Se  
Albuquerque NM 87108

**(505) 247-9771**

04212008 (505) 250-1120 p

ivs@lobo.net

**2005 Volvo S60 License: 3163/0408 Odometer: 48841 Vin: YV1RS612752430408  
B5244S AW55-50/51SN ABS Barents blue**

**PRESALE INSPECTION AND BASIC MAINTENANCE -**

Labor performed on this job:

Labor 1 Labor Rate: \$85.00 \$85.00  
INSPECT VEHICLE IN ORDER TO DETERMINE SERVICE  
NEEDS BEFORE SALE  
997

Parts: \$0.00  
Labor: \$85.00  
**Job Subtotal: \$85.00**

**SERVICE WORK**

Labor performed on this job:

Labor 0.8 Labor Rate: \$85.00 \$68.00  
Oil and filter service. Replaced wiper blades  
997

Parts required on this job:

Haz Mat Fee	6	\$0.25	\$1.50
10W30	6	\$2.50	\$15.00
OIL FILTER, INSERT 70 99-04 V70 99+, S80, S40 -MID04, V40 -04, S60, XC90 (EXC 07+ 6CYL)	1	\$8.42	\$8.42
WASHER, DRAIN PLUG - ALUMINIUM 850, 960, 70, 90, S80, 40, V50, S60, XC90	1	\$0.64	\$0.64
GASKET, OIL FILLER CAP 200 4CYL, 700 4CYL, 900, 850, 90	1	\$1.50	\$1.50

Parts: \$68.53  
Labor: \$68.00  
**Job Subtotal: \$136.53**

**MASTER KEY WITH SOFTWARE DOWNLOAD**

Labor performed on this job:

Labor 0.5 Labor Rate: \$85.00 \$42.50  
Supply new master key and download software to make it  
operate  
1

Parts required on this job:

Parts: \$84.05  
Labor: \$42.50  
**Job Subtotal: \$126.55**

## KEYLESS ENTRY REMOTE

Labor performed on this job:

Labor 0.5 Labor Rate: \$85.00 \$42.50

Supply new keyless entry remote and download software to make it work.

1

Parts required on this job:

Parts: \$149.23

Labor: \$42.50

**Job Subtotal:** \$191.73

## SHOP INFORMATION AND SUPPORT

Labor performed on this job:

Labor 0.16 Labor Rate: \$85.00 \$13.60

The information age has arrived and it is expensive. We currently spend in excess of \$1000 monthly for current Volvo service information and hardware associated with its use. Additionally, the myriad of items never invoiced i.e. Hardware, chemicals, cleaner and other supplies continue to escalate in cost. Our shuttle service is another new expense. This surcharge is to help recover a portion of these costs without increasing our labor rate. Thank you for your understanding and support.

9

Parts: \$0.00

Labor: \$13.60

**Job Subtotal:** \$13.60

## BRAKES, FRONT WITH MACHINED ROTORS AND PADS

Labor performed on this job:

Labor 1.6 Labor Rate: \$85.00 \$136.00

Test drive in an attempt to duplicate customer complaint, if any. Examine wheel brakes for wear and deterioration. Remove and machine rotors, apply a non-directional swirl finish, reinstall. Examine calipers for leakage, clean and lubricate them as needed. Treat brake pad friction surfaces with BG brand noise control compound and lubricate pad backing surfaces with copper base antiseize. Reassemble torquing all threaded hardware and test drive to verify repairs.

997

Parts required on this job:

Parts: \$110.77

Labor: \$136.00

**Job Subtotal:** \$246.77

## EMISSION TEST(FLEET)

Labor performed on this job:

Labor 0.1882 Labor Rate: \$85.00 \$16.00

PERFORM BERNILILLO COUNTY EMISSION TEST

1

Parts: \$0.00

Labor: \$16.00

**Job Subtotal:** \$16.00

**Estimate of Repair**

Parts:	\$412.58
Labor:	\$403.60
Discounts:	<b>(\$97.94)</b>
Subtotal:	\$816.18
Tax:	\$0.00
<b>Total:</b>	<b>\$718.24</b>